




United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Price Field Office
125 South 600 West
Price, UT 84501
<http://www.blm.gov/utah/price/>



IN REPLY REFER TO:

3809
(U070)
UTU-69855
UTU-69856
UTU-69857

RECEIVED

OCT 05 2009

DIV. OF OIL, GAS & MINING

Paul Baker
State of Utah
Department of Natural Resources
Division of Oil, Gas & Mining
1594 W. North Temple, Suite 1210
Salt Lake City, Utah 84114-5801

**RE: Bond Review for Mining claims S/015/046; S/015/043; S/015/053
Daddy Dearest, Miller Rock, Emeryide Mines; T. 22 S., R. 6 E., Section 26; Emery County, Utah**

Dear Mr. Baker:

A compliance examination and file review of the Daddy Dearest, Miller Rock, and Emeryide humate mines, in Emery County, Utah, was conducted July 14, 2009 by the Bureau of Land Management's (BLM) Price Field Office. The inspection revealed that active mining at all three operations has ceased and that two of the mines, Daddy Dearest and Miller Rock, have an excessive amount of scrap, trash and/or wreckage on site. Most notably, the Miller Rock mine has an abandoned, dilapidated camper and Daddy Dearest is storing potentially hazardous wastes in drums and lead-acid batteries. The file review showed that there have been several attempts over the past several years to persuade the Clark's to clean up their facilities and bond amounts need to be adjusted to coincide with current site-conditions.

The BLM has calculated bonds for the Clark mines as follows:

Emeryide	UTU-69855; S/015/053 \$5,400
Daddy Dearest	UTU-69856; S/015/046 \$30,000
Miller Rock	UTU-69857; S/015/043 \$25,400

It is BLM's understanding that you will contact each of the claimants above notifying them of the bond increases. If you have any question, please call Chris Conrad at 435-636-3667.

Sincerely,

Jerry Kenczka
Field Manager

Cc: Opie Abeyta

0002